

# DUBAI MUNICIPALITY

Environment Department  
Environment Protection & Safety Section  
Tel: 2064244 / 2064245 Fax: 2270160



بلدية دبي  
إدارة البيئة  
قسم حماية البيئة و السلامة

## BANNED TOYS

### SEPTEMBER 2007

<p>Name of Toy : CHANTICLEER PEEPY Item No. : PD333 Batch No. : -- Manufacturer : -- Country of Origin : China Report No. : TR-4804 Report Date : 29 / 08 /07 Hazard :</p> <ul style="list-style-type: none"><li>• The toy contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.</li></ul>	
<p>Name of Toy : CIRCLING MUSIC RABBIT Item No. : XQ 20898 Batch No. : -- Manufacturer : -- Country of Origin : China Report No. : TR-4813 Report Date : 30 / 08 /07 Hazard :</p> <ul style="list-style-type: none"><li>• The toy has small parts components when subjected to tests and could pose choking hazard for very young children.</li><li>• The thickness of the cord is less than the required by the standard which poses strangulation risk for very young children.</li><li>• All parts of the toy except the yellow ball are potential impaction hazard for children who are too young to sit up unaided.</li></ul>	
<p>Name of Toy : SUPER VEHICLE Item No. : F102 Batch No. : -- Manufacturer : -- Country of Origin : China Report No. : TR-4815 Report Date : 30 / 08 /07 Hazard :</p> <ul style="list-style-type: none"><li>• The car and the jet ski contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.</li></ul>	

Name of Toy : NEW AUTO GPR3  
Item No. : 867  
Batch No. : --  
Manufacturer : --  
Country of Origin : China  
Report No. : TR-4800  
Report Date : 29 / 08 /07  
Hazard :

- The yellow car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : TOYS  
Item No. : SY-512-2  
Batch No. : --  
Manufacturer : --  
Country of Origin : China  
Report No. : TR-4784  
Report Date : 26 / 08 /07  
Hazard :

- The car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : TOYS - CARS  
Item No. : 831-2  
Batch No. : --  
Manufacturer : --  
Country of Origin : China  
Report No. : TR-4816  
Report Date : 30 / 08 /07  
Hazard :

- The car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : FASTER SPEED  
Item No. : 2720 and 2710A  
Batch No. : --  
Manufacturer : --  
Country of Origin : China  
Report No. : TR-4801  
Report Date : 29 / 08 /07  
Hazard :

- The yellow car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



<p> <i>Name of Toy</i> : RACING ROCKET  <i>Item No.</i> : 3038  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4785  <i>Report Date</i> : 26 / 08 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The motorcycle contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	
<p> <i>Name of Toy</i> : TOYS  <i>Item No.</i> : KY6001  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4802  <i>Report Date</i> : 29 / 08 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• An opening in the seams of the soft toy balls was found allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.</li> </ul>	
<p> <i>Name of Toy</i> : ORANGE BEAR SOFT TOY  <i>Item No.</i> : 5040 B  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-812  <i>Report Date</i> : 30 / 08 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• An opening in the seams of the soft toy balls was found allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.</li> </ul>	
<p> <i>Name of Toy</i> : MAX SUPER SPEED POWERFUL TRUCK  <i>Item No.</i> : 8868-5  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4796  <i>Report Date</i> : 28 / 08 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The green car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	

<p> <i>Name of Toy</i> : SUPER CAR  <i>Item No.</i> : SV.2051  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4790  <i>Report Date</i> : 28 / 08 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	
<p> <i>Name of Toy</i> : RACING – THE FASTER SPEED  <i>Item No.</i> : 438  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4767  <i>Report Date</i> : 21 / 08 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The red and yellow car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	
<p> <i>Name of Toy</i> : BABY TREASURE PLAY SET  <i>Item No.</i> : 628 (A,B,C)  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4776  <i>Report Date</i> : 23 / 08 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The rattles produces cracks, small parts and sharp points when subjected to strength tests and could pose multiple hazard for very young children.</li> <li>• Two rattles are potential impaction hazard for children who are too young to sit up unaided.</li> </ul>	
<p> <i>Name of Toy</i> : GLAMOUR VANITY  <i>Item No.</i> : 3657600  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4814  <i>Report Date</i> : 30 / 08 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The plastic sheeting of the flexible plastic bag is less than the required by the standard which could adhere to a child's mouth and nose making it impossible to breathe.</li> <li>• The toys has components made of glass which could be broken and pose injuries related to cuts, lacerations, punctures of the skin, etc.</li> <li>• The toy has components which are tested for sharp points which presents an unreasonable risk of injury like punctures of the skin, etc.</li> </ul>	

Name of Toy : BAO BEI ZHIYUE  
Item No. : 2008B-20  
Batch No. : --  
Manufacturer : --  
Country of Origin : China  
Report No. : TR-4782  
Report Date : 26 / 08 /07  
Hazard :

- The toy rattle is a potential impaction hazard for children who are too young to sit up unaided.



Name of Toy : SOFT STUFFED BALL  
Item No. : --  
Batch No. : --  
Manufacturer : --  
Country of Origin : China  
Report No. : TR-4799  
Report Date : 29 / 08 /07  
Hazard :

- An opening in the seams of the soft toy balls was produced when subjected to tension test allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.
- The soft toy balls contains high levels of lead when tested. High levels of lead are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : SUPER SPORT  
Item No. : 1879  
Batch No. : --  
Manufacturer : --  
Country of Origin : China  
Report No. : TR-4780  
Report Date : 26 / 08 /07  
Hazard :

- The car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : MONSTER CASTLE SET  
Item No. : 1879  
Batch No. : --  
Manufacturer : --  
Country of Origin : China  
Report No. : TR-4780  
Report Date : 26 / 08 /07  
Hazard :

- The car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : TRUCK TRAILBLAZER  
 Item No. : 2601  
 Batch No. : --  
 Manufacturer : --  
 Country of Origin : China  
 Report No. : TR-4797  
 Report Date : 28 / 08 /07  
 Hazard :

- The driver's cab contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : SUPER SPORT & GAME  
 Item No. : --  
 Batch No. : --  
 Manufacturer : --  
 Country of Origin : China  
 Report No. : TR-4798  
 Report Date : 28 / 08 /07  
 Hazard :

- An opening in the seams of the soft toy balls was found allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.
- The soft toy balls contains high levels of lead when tested. High levels of lead are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : POWER CARS  
 Item No. : 663E-3  
 Batch No. : --  
 Manufacturer : --  
 Country of Origin : China  
 Report No. : TR-4772  
 Report Date : 23 / 08 /07  
 Hazard :

- The yellow and green car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : SUPER HERO  
 Item No. : G.H. 7235C  
 Batch No. : --  
 Manufacturer : --  
 Country of Origin : China  
 Report No. : TR-4775  
 Report Date : 23 / 08 /07  
 Hazard :

- The white and blue car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : SOFT TOY DOLL  
Item No. : --  
Batch No. : --  
Manufacturer : --  
Country of Origin : China  
Report No. : TR-4827  
Report Date : 05 / 09 /07  
Hazard :

- An opening in the seams of the soft toy balls was produced when subjected to tension test allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.



Name of Toy : SOFT TOY DOG  
Item No. : 260802-12  
Batch No. : --  
Manufacturer : --  
Country of Origin : China  
Report No. : TR-4820  
Report Date : 03 / 09 /07  
Hazard :

- An opening in the seams of the soft toy balls was produced when subjected to tension test allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.



Name of Toy : SOFT TOY DOG  
Item No. : 230435-8E  
Batch No. : --  
Manufacturer : --  
Country of Origin : China  
Report No. : TR-4824  
Report Date : 04 / 09 /07  
Hazard :

- An opening in the seams of the soft toy balls was produced when subjected to tension test allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.







Name of Toy : SOFT TOY DOG  
Item No. : 260802-12  
Batch No. : --  
Manufacturer : --  
Country of Origin : China  
Report No. : TR-4820  
Report Date : 03 / 09 /07  
Hazard :





- An opening in the seams of the soft toy balls was found allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.




<p> <i>Name of Toy</i> : ADVENTURE FIELD CAR  <i>Item No.</i> : 868A  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4828  <i>Report Date</i> : 05 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The yellow car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	
<p> <i>Name of Toy</i> : CATENA  <i>Item No.</i> : UD578  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4831  <i>Report Date</i> : 05 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The yellow car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	
<p> <i>Name of Toy</i> : DANNY'S DIVING ADVENTURE  <i>Item No.</i> : 04010  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4823  <i>Report Date</i> : 03 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The toy produces cracks and small parts when subjected to impact test and could pose multiple hazards for very young children.</li> </ul>	
<p> <i>Name of Toy</i> : JIGGLY JIMMY  <i>Item No.</i> : 05040  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4822  <i>Report Date</i> : 03 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The toy produces cracks when subjected to drop test and could pose multiple hazards for very young children.</li> </ul>	
<p> <i>Name of Toy</i> : CHAMPION THUNDER  <i>Item No.</i> : YD8007  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4863  <i>Report Date</i> : 11 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The yellow and green car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	



<p> <i>Name of Toy</i> : FIGHTER RACING  <i>Item No.</i> : J999  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4864  <i>Report Date</i> : 11 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The yellow car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	
<p> <i>Name of Toy</i> : GALLOP  <i>Item No.</i> : 218  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4855  <i>Report Date</i> : 10 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The motorcycle contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	
<p> <i>Name of Toy</i> : HORRIBLE MAKE-UP TEETH  <i>Item No.</i> : 70376  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4851  <i>Report Date</i> : 10 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The teeth contain high levels of lead when tested. High levels of lead are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	
<p> <i>Name of Toy</i> : HORRIBLE MAKE-UP TEETH  <i>Item No.</i> : 70377  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4851  <i>Report Date</i> : 10 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The teeth contain high levels of lead when tested. High levels of lead are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	
<p> <i>Name of Toy</i> : HORRIBLE MAKE-UP TEETH  <i>Item No.</i> : 70377  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4851  <i>Report Date</i> : 10 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The teeth contain high levels of lead when tested. High levels of lead are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	

<p> <i>Name of Toy</i> : <b>BABY GIFT</b>  <i>Item No.</i> : <b>3219</b>  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : <b>China</b>  <i>Report No.</i> : <b>TR-4861</b>  <i>Report Date</i> : <b>11 / 09 /07</b>  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• <b>The phone toy and the rattle with rings produce high pressure sound which exceeds the limit specified in the standard and could cause hearing defects for children.</b></li> <li>• <b>The rattle with rings produces cracks and small parts when subjected to drop test which could cause multiple hazards for very small children.</b></li> </ul>	
<p> <i>Name of Toy</i> : <b>HANGING SOFT TOY WITH SPRING</b>  <i>Item No.</i> : <b>R184</b>  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : <b>China</b>  <i>Report No.</i> : <b>TR-4873</b>  <i>Report Date</i> : <b>13 / 09 /07</b>  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• <b>An opening in the seams of the soft toy was produced when subjected to tension test allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.</b></li> <li>• <b>The end of the spring wire is tested for sharp point which could cause unreasonable risk of injury like punctures of the skin, etc.</b></li> </ul>	
<p> <i>Name of Toy</i> : <b>SOFT TOY SHEEP</b>  <i>Item No.</i> : <b>6716</b>  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : <b>China</b>  <i>Report No.</i> : <b>TR-4869</b>  <i>Report Date</i> : <b>12 / 09 /07</b>  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• <b>An opening in the seams of the soft toy was produced when subjected to tension test allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.</b></li> </ul>	
<p> <i>Name of Toy</i> : <b>MADAM DAISY</b>  <i>Item No.</i> : <b>R184</b>  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : <b>China</b>  <i>Report No.</i> : <b>TR-4874</b>  <i>Report Date</i> : <b>12 / 09 /07</b>  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• <b>An opening in the seams of the soft toy was produced when subjected to tension test allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.</b></li> </ul>	

<p> <i>Name of Toy</i> : SOFT TOY PEACOCK  <i>Item No.</i> : 6716  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4872  <i>Report Date</i> : 12 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• An opening in the seams of the soft toy was found allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.</li> </ul>	
<p> <i>Name of Toy</i> : HOME KIDS COW  <i>Item No.</i> : --  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4859  <i>Report Date</i> : 10 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• An opening in the seams of the soft toy was found allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.</li> </ul>	
<p> <i>Name of Toy</i> : LIGHTING SPEED  <i>Item No.</i> : 5888-8A  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4879  <i>Report Date</i> : 13 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The cars contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	
<p> <i>Name of Toy</i> : ROBOTS  <i>Item No.</i> : 7799  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4877  <i>Report Date</i> : 13 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The red robot contains high levels of lead when tested. High levels of lead are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	
<p> <i>Name of Toy</i> : SUPER RACING  <i>Item No.</i> : 13910  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4878  <i>Report Date</i> : 13 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The red and black car contains high levels of lead when tested. High levels of lead are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	

Name of Toy : SPIDER-MAN 3  
 Item No. : 23816-3  
 Batch No. : --  
 Manufacturer : --  
 Country of Origin : China  
 Report No. : TR-4882  
 Report Date : 13 / 09 /07  
 Hazard :

- The pin of the spider-man logo is tested for sharp point which could cause unreasonable risk of injury like punctures of the skin, etc.



Name of Toy : HAPPY FUN  
 Item No. : 286-8  
 Batch No. : --  
 Manufacturer : --  
 Country of Origin : China  
 Report No. : TR-4898  
 Report Date : 17 / 09 /07  
 Hazard :

- The rattles produce high pressure sound which exceeds the limit specified in the standard and could cause hearing defects for children.
- The rattle with rings produces cracks and small parts when subjected to drop test which could cause multiple hazards for very small children.
- The toy rattle is a potential impaction hazard for children who are too young to sit up unaided.
- The toy contains small balls capable of blocking the airway at the back of the mouth and upper throat.



Name of Toy : BABY TOYS – ZHIYUE BAObEI  
 Item No. : 2008C-61  
 Batch No. : --  
 Manufacturer : --  
 Country of Origin : China  
 Report No. : TR-4888  
 Report Date : 17 / 09 /07  
 Hazard :

- The rattles produce high sound levels which exceed the limit specified in the standard and could cause hearing defects for children.
- The rattle with rings produces cracks and small parts when subjected to drop test which could cause multiple hazards for very small children.
- The toy rattle is a potential impaction hazard for children who are too young to sit up unaided.



Name of Toy : MUSICAL BB MOBILE  
 Item No. : 2205  
 Batch No. : --  
 Manufacturer : --  
 Country of Origin : China  
 Report No. : TR-4897  
 Report Date : 17 / 09 /07  
 Hazard :

- The circle wire between musical box and hanging toy is deemed to be sharp points and may present unreasonable risk of injury like punctures of the skin, etc.
- The rattles produces cracks and small parts when subjected to drop and impact tests posing multiple hazards for very small children.
- The baby elephant and heart is a potential impaction hazard for children who are too young to sit up unaided.



<p> <i>Name of Toy</i> : HAMBURGER CAR  <i>Item No.</i> : 025  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4887  <i>Report Date</i> : 16 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The toy contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.</li> </ul>	
<p> <i>Name of Toy</i> : SOFT TOY CAMEL BAHR  <i>Item No.</i> : --  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4912  <i>Report Date</i> : 23 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The bell could easily detached and produce small parts which could pose as choking hazards for small children.</li> <li>• An opening in the seams of the soft toy was found allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.</li> <li>• The cord attached to the soft toy is too long which exceeds the required length based on the standard which could pose strangulation hazard for children.</li> </ul>	
<p> <i>Name of Toy</i> : SUPER SPORT AND GAME  <i>Item No.</i> : --  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4896  <i>Report Date</i> : 17 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• An opening in the seams of the soft toy balls was found allowing the filling materials to be easily accessible which could pose ingestion and choking hazard risk.</li> </ul>	
<p> <i>Name of Toy</i> : MUSICAL RADIO  <i>Item No.</i> : 918  <i>Batch No.</i> : --  <i>Manufacturer</i> : --  <i>Country of Origin</i> : China  <i>Report No.</i> : TR-4884  <i>Report Date</i> : 16 / 09 /07  <i>Hazard</i> : </p> <ul style="list-style-type: none"> <li>• The toy produces cracks and small parts when subjected to impact tests posing multiple hazards for very small children.</li> </ul>	

*Name of Toy* : **SHAPE SORTER**  
*Item No.* : **829**  
*Batch No.* : --  
*Manufacturer* : --  
*Country of Origin* : **China**  
*Report No.* : **TR-4889**  
*Report Date* : **17 / 09 /07**  
*Hazard* :

- **The toy produces cracks and small parts when subjected to impact tests posing multiple hazards for very small children.**

