






BANNED TOYS

MARCH 2007

<p><i>Name of Toy</i> : SUPER LION <i>Item No.</i> : 2298 <i>Batch No.</i> : -- <i>Manufacturer</i> : -- <i>Country of Origin</i> : China <i>Report No.</i> : TR-4006 <i>Report Date</i> : 05/ 03 /07 <i>Hazard</i> :</p> <ul style="list-style-type: none">• The lion contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.	
<p><i>Name of Toy</i> : GROWING ANIMALS <i>Item No.</i> : 21907 <i>Batch No.</i> : -- <i>Manufacturer</i> : -- <i>Country of Origin</i> : China <i>Report No.</i> : TR-4042 <i>Report Date</i> : 12/ 03 /07 <i>Hazard</i> :</p> <ul style="list-style-type: none">• The orange fish expands by 106%, 131 % and 81 % when tested which could pose as choking and ingestion hazard for small children.	
<p><i>Name of Toy</i> : HANGING DECORATIONS <i>Item No.</i> : JB55-6C <i>Batch No.</i> : -- <i>Manufacturer</i> : -- <i>Country of Origin</i> : China <i>Report No.</i> : TR-4040 <i>Report Date</i> : 13/ 03 /07 <i>Hazard</i> :</p> <ul style="list-style-type: none">• The edges of the metal screw head contains burr capable of causing wound or abrasion for very young children.• Cord used on the toy is too thin which could form noose around the neck and could pose as strangulation of very young children.• Part of the musical box and the 2 hanging characters pose as impaction hazard for children.	

Name of Toy : ARMY HEROES FORCE PEACE KEEPERS
 Item No. : --
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4044
 Report Date : 13 / 03 /07
 Hazard :

- The tractor and the tank contains high levels of lead and chromium. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : FUN BABY TOY
 Item No. : 3312
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4048
 Report Date : 13 / 03 /07
 Hazard :

- 8 baby rattles produces cracks, small parts and sharp points when tested which could pose hazards for very young children.



Name of Toy : MY FIRST WATERCOLOUR PAINTS, BRUSHES AND PALLETE SET
 Item No. : --
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4057
 Report Date : 05/ 03 /07
 Hazard :

- The green paint and yellow contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could



Name of Toy : FUNNY TOYS - RATTLE
 Item No. : --
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4063
 Report Date : 14 / 03 /07
 Hazard :

- 2 rattles produces cracks, small parts, small balls and sharp points when tested which could pose multiple hazards for very young children.



Name of Toy : **BABY TOYS RATTLE**
 Item No. : **CV 1003**
 Batch No. : --
 Manufacturer : --
 Country of Origin : **China**
 Report No. : **TR-4061**
 Report Date : **14 / 03 /07**
 Hazard :

- **2 rattles produces cracks when tested which could later on produce small parts and sharp points when subjected to continuous use and could pose multiple hazards for very young children.**
- **5 rattles is considered as impaction hazard for very young children who are too young to sit unaided.**



Name of Toy : **BABY TOYS - RATTLE**
 Item No. : **912**
 Batch No. : --
 Manufacturer : --
 Country of Origin : **China**
 Report No. : **TR-4062**
 Report Date : **14 / 03 /07**
 Hazard :

- **5 rattles produces cracks, small parts and sharp points when tested which could pose multiple hazards for very young children.**



Name of Toy : **RACER**
 Item No. : **235**
 Batch No. : --
 Manufacturer : --
 Country of Origin : **China**
 Report No. : **TR-4053**
 Report Date : **14/ 03 /07**
 Hazard :

- **The yellow car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.**



Name of Toy : **SUPER CHAMPION**
 Item No. : **399-1C**
 Batch No. : --
 Manufacturer : --
 Country of Origin : **China**
 Report No. : **TR-4066**
 Report Date : **15/ 03 /07**
 Hazard :

- **The light green car, yellow car and red car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.**



Name of Toy : FIRST REAL
 Item No. : 828
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4068
 Report Date : 15/ 03 /07
 Hazard :

- The green car and yellow car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : TOYS
 Item No. : LD 3468A
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4065
 Report Date : 15/ 03 /07
 Hazard :

- The yellow car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : JOYFUL MUSICAL MOBILE
 Item No. : 999-7A
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4076
 Report Date : 18 / 03 /07
 Hazard :

- The locks between the two arms of the mobile fits is considered as small part and could be pose as choking hazards for very young children.
- The hanging 2 fish characters produces cracks, small parts and sharp points when tested which could pose multiple hazards for very young children.
- The thickness and length of the cord provided unto the musical mobile does not conform with the standards which could pose as strangulation hazard for very young children.
- The fish character is considered as impaction hazard for very young children who are too young to sit up unaided.



Name of Toy : TOYS
 Item No. : 501-1
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4084
 Report Date : 19/ 03 /07
 Hazard :

- The green car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : FIRE ENGINE
 Item No. : 3988-6
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4080
 Report Date : 19/ 03 /07
 Hazard :

- The yellow car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : PARKING LOT
 Item No. : 2204
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4090
 Report Date : 21/ 03 /07
 Hazard :

- The coating of paint from the body of the car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : H2 Hummer – Nonsuch Jeep
 Item No. : 2265
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4092
 Report Date : 21/ 03 /07
 Hazard :

- The body of the green and yellow car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : Doll
 Item No. : --
 Batch No. : --
 Manufacturer : --
 Country of Origin : --
 Report No. : TR-4126
 Report Date : 29/ 03 /07
 Hazard :

- The yellow textile shirt of the doll contains high levels of lead when tested. High levels of lead are toxic if ingested by young children and could cause adverse health effects.
- The metal zipper of the shirt is tested for sharp points which could pose injury like punctures of the skin.
- The filling materials at the back of the head of the toy is accessible posing as choking hazard for small children.



Name of Toy : ANTI - TERRORISM
 Item No. : 1688-4A
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4134
 Report Date : 29/ 03 /07
 Hazard :

- The multicolor coating of paint and plastic of the car contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : F-22 MUL – Fighter Plane
 Item No. : 236
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4134
 Report Date : 29/ 03 /07
 Hazard :

- The body of the plane contains high levels of lead and chromium when tested. High levels of lead and chromium are toxic if ingested by young children and could cause adverse health effects.



Name of Toy : Intelligence Funny Toys
 Item No. : YM-670
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4120
 Report Date : 28 / 03 /07
 Hazard :

- The yellow circle sharp rattle and the ball sharp rattle produce cracks when tested which could pose hazards for very young children.



Name of Toy : Baby's Shake Rattle
 Item No. : 5508
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4117
 Report Date : 28 / 03 /07
 Hazard :

- 4 rattles produce cracks and small parts when tested which could pose multiple hazards for very young children.
- The handle of the maracas is considered as impaction hazard for very young children.



Name of Toy : Baby Play Gym
 Item No. : 885A
 Batch No. : --
 Manufacturer : --
 Country of Origin : China
 Report No. : TR-4121
 Report Date : 28 / 03 /07
 Hazard :

- The roller ball, yellow/blue bear and yellow bear produce cracks, small parts, sharp edge and sharp points when tested which could pose multiple hazards for very young children.
- The yellow/blue bear and yellow bear is considered as impaction hazard for very young children who are too young to sit-up unaided.



Name of Toy : **Rolling Bell With Music**
Item No. : **20821**
Batch No. : --
Manufacturer : --
Country of Origin : **China**
Report No. : **TR-4122**
Report Date : **29 / 03 /07**
Hazard :

- **The small orange hanging heat character detached and produces small parts when tested which could pose as choking hazard for babies.**
- **The hanging balls produce cracks, small parts, sharp edge and sharp points when tested which could pose multiple hazards for very young children.**
- **The hook of the musical mobile is considered as impaction hazard for very young children who are too young to sit-up unaided.**

